IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Application: 09/651,159
Filing Date: August 30, 2000
Inventor: Ole Bentz
Title: Overflow Detection and Clamping with Parallel Operand Processing for Fixed-Point Multipliers
Examiner: Chat C. Do
Art Unit: 2124
Attorney Docket: MTI-31072 (15225.0011)
Confirmation No.: 2115

CERTIFICATION UNDER 37 CFR 1.8(a) and 1.10

I hereby certify that, on the date shown below, this correspondence is being:

Mailing

☒ deposited with the U.S. Postal Service in an envelope addressed to the Mailstop RCE, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

37 CFR 1.8(a)	37 CFR 1.10

☐ with sufficient postage as first class mail ☒ As "Express Mail Post Office to Addressee" Mailing Label No. EV405079533US

Transmission

☐ transmitted by facsimile to Fax No. (703) 872-9306 addressed to Examiner Do at the U.S. Patent and Trademark Office.

Date: _September 7, 2004_   _Jon R. Hauk_

Mail Stop RCE
Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

SUPPLEMENT RESPONSE AFTER FINAL

Dear Sir:

Introductory Comments begin on:	page 2 of 6
Remarks begin on:	page 3 of 6
Conclusion begins on:	page 5 of 6
Extension of Time begins on:	page 6 of 6

MKE/968103.1

INTRODUCTORY COMMENTS

After careful review, Applicant hereby responds to an August 4, 2004 Advisory Action regarding the above-referenced patent application. In view of this Response, Applicant respectfully requests reconsideration of said application.

Applicant has not added new matter with this Response, and intends the scope of the invention and previously pending claims to be the same before and after this Response. Indeed, Applicant only offers this Response to clarify the invention for the Examiner, and to assist the Examiner's understanding of the same. More specifically, Applicant has not intended this Response to effectuate a narrowing of the claims, foreclose techniques that are not reasonably foreseeable at this time, or effect the applicability and scope of the Doctrine of Equivalents.

MKE/968103.1